

# Brumley South, Inc.

**We Did The Impossible Again!**

**GSI Scanner Mirror Assembly Now Supported**  
Tencor Surfscan 6100, 6200, 6400 Series

### Scanner Part Numbers:

**346888, 289167, 162930, 204587, 3005502, 3005507-Others**

### Tencor Surfscan 6000 Series

#### **THE PROBLEM:**

"Hard Down" GSI Mirror Scanner is

BAD

OEM no longer supports and has

ZERO STOCK.

#### **THE SOLUTION:**

Brumley South now has in **STOCK**  
Mirror Scanner assemblies.

**Same Day Shipping**

#### DETAILS:


Refurbished back to OEM condition.

Tencor Tested in Surfscan .

This should be installed by Tech that

has Tencor Optical Alignment  
Training.

**1 Year Warranty**



**PRICING:**  
Exchange price = \$17,500.00  
Typically in stock  
Repair price = \$15,500.00  
8 week lead time

#### Contact Information

Brumley South, Inc

422 N. Broad Street

Mooreville, NC 28115

Ph (704) 664-9251

Purchasing: Cheryl Gregory Ext. 204

Email: orders@brumleysouth.com

www.brumleysouth.com