



Brumley South, Inc.

We Did The Impossible Again!

GSI Scanner Mirror Assembly Now Supported
Tencor Surfscan 6100, 6200, 6400 Series

Scanner Part Numbers:

346888, 289167, 162930, 204587, 3005502, 3005507-Others

Tencor Surfscan 6000 Series

THE PROBLEM:

“Hard Down” GSI Mirror Scanner is
BAD
OEM no longer supports and has
ZERO STOCK.

THE SOLUTION:

Brumley South now has in STOCK
Mirror Scanner assemblies.

Same Day Shipping

DETAILS:

Refurbished back to OEM condition.
Tencor Tested in Surfscan .
This should be installed by Tech that
has Tencor Optical Alignment
Training.

1 Year Warranty



Contact Information

Brumley South, Inc
422 N. Broad Street
Mooresville, NC 28115
Ph (704) 664-9251
Purchasing: Cheryl Gregory Ext. 204
Sales: Tom Norment Ext. 202
Email: orders@brumleysouth.com
www.brumleysouth.com