



Brumley South, Inc.

Tencor Surfscan PCB Repair 6100, 6200, 6220, 6400, 6420

We offer KLA-Tencor World Class Circuit Board Repairs / Exchange Support

BSI offers Support Services on your Tencor Surfscan Circuit Boards and Assemblies.

Services Include:

1. In House Service.
2. Enhancement Upgrades
3. Reliability Upgrades
4. Microscope Inspection
5. Surface Mount Soldering Experts
6. Up to 12 Month Warranties
7. Tencor Tested in Clean Room
8. NIST Standards Referenced.
9. QA Run time Tool Test 48 hours minimum.


Expedite Repair Services available.

Exchange Inventory for Quick Ship!

**Now Available!
Trenton Computer Board Replacement!
USB-2.0 ready. Solid State Drives.**

General PCB Description


Analog , Haze, Peak, Particle Area, Below Wafer Detector, GPIO, INSW....we do them All!




Huntron Flying Probe Test Bed



Advanced Microscope Inspection.
Full Rework Capability



Dedicated Test Beds



Parts in Stock!

Contact Information

Brumley South, Inc
Cheryl Gregory
422 N. Broad Street
Mooresville, NC 28115
Ph (704) 664-9251 Ext. 204

Email: orders@brumleysouth.com
www.brumleysouth.com

REV 2-16-21

Fixing the Impossible to Repair... EVERY Day!